2023.9.7



6.5cm



3x2.9cm

Hot surface



5.8x4cm



7.0x2.5cm









MUST WEAR EYE AND
EAR PROTECTION AND
HEAVY DUTY PROTECTIVE
CLOTHING/BOOTS

8.6x7.2cm



DO NOT PUT HANDS INTO HOPPER AND/ OR FUNNEL

8.6x7.2cm

CAUTION

- Check the oil level before starting the machine.
- Ensure all levers are in the fast/ON position.
- Do not operate indoors or in poorly ventilated places.
- All operators must read the instruction manual before use.
- Keep bystanders at least 10m away

12.7x5.2cm