



DANGER



CAUTION:

Contains flammable gases. This cooler contains a small quantity of R600a refrigerant gas within it's sealed system. Repairs should only be performed by a suitably qualified person. The insulation foam contains **CYCLOPENTANE** which is also flammable.